

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 5 77 WEST JACKSON BOULEVARD CHICAGO, ILLINOIS 60604

SUBJECT: CLEAN AIR ACT INSPECTION REPORT

Nu-Way Industries, Des Plaines, Illinois

FROM: Vicky Mei, Environmental Engineer

AECAB (IL/IN)

THRU: Nathan Frank, Section Supervisor

AECAB (IL/IN)

TO: File

BASIC INFORMATION

Facility Name: Nu-Way Industries, Inc.

Facility Location: 555 Howard Avenue, Des Plaines, Illinois 60018

Date of Inspection: August 5, 2022

EPA Inspector(s):

1. Vicky Mei, Environmental Engineer

Other Attendees:

1. Steve Wiseman, Executive Vice President/COO

2. Mary Howard, Executive Vice President/CFO

Contact Email Address: wisemans@nu-way.net and howardm@nu-way.net

Purpose of Inspection: Clean Air Act inspection

Facility Type: Metal powder coating

Regulations Central to Inspection: Evaluate the applicability of permitting requirements under

the Illinois State Implementation Plan and the Clean Air Act

Arrival Time: 1:30 PM **Departure Time:** 3:00 PM

Inspection Type:

☑ Unannounced Inspection☐ Announced Inspection

OPENING CONFERENCE

\boxtimes	Presented Credentials
\boxtimes	Stated authority and purpose of inspection
\boxtimes	Provided Small Business Resource Information Sheet
	Small Business Resource Information Sheet not provided
\boxtimes	Provided CBI warning to facility

The following information was obtained verbally from Nu-Way Industries unless otherwise noted.

Process Description:

The facility operates a variety of processes, including metal punching, laser cutting, press brake forming, hardware insertion, spot and resistance welding, robotic welding, traditional welding, assembly, grinding, polishing, machining, stamping, and powder coating. The welding areas, laser cutting stations, and grinding stations have dust collectors. For the two powder coating lines, the metal parts are washed and dried on a conveyor belt. The powder is sprayed on the metal parts and heated in an oven to liquify and dry the powder. The powder in the negative-pressure spray booth is controlled by a cyclone. The process is continuous and is stopped when there is a color change.

Staff Interview:

The facility has been at its current location since 1994 and has about 240 full-time employees. One of the automation systems was added in 2003. A small plastics vacuum forming station was added 4 to 5 years ago.

TOUR INFORMATION

EPA Tour of the Facility: Yes

Photos and/or Videos: were not taken during the inspection.

Field Measurements: were not taken during this inspection.

CLOSING CONFERENCE

Requested documents:

Most recent Illinois EPA permit

DIGITAL SIGNATURES

Report Author:	 	
Section Supervisor:		